MAIL THE COMPLETED FORM TO: The appropriate EPA Regional or State Office.	United States Environmental Protection Agency RCRA SUBTITLE C SITE IDENTIFICATION FORM - 2007					
Reason for Submittal (see instructions on page 9)	A. Reason for Submittal:					
MARK ALL BOX(ES) THAT APPLY	As a component of a Revised RCRA Hazardous Waste Part A Permit Application (Amendment #) As a component of Hazardous Waste Report.					
2. Site EPA ID Number (page 10)	EPAID Number: IAD073489288					
3. SiteName (page 10)	Site Name: Industrial Laminates/Norplex Inc	•				
Site Location Information	Street Address: 665 Lybrand St.	PO Box 977				
(page 10)	City, Town or Village: Postville	State: IA				
	County Name: ALLAMAKEE	Zip Code: 52162				
5. Site Land Type (page 10)	Site Land Type: X Private County District Federal	☐ Indian ☐ Municipal ☐ State ☐ Other				
6. North American Industry Classification System (NAICS) Code(s) for the	A. 326130 B.					
Site (page 10)	C. D.					
7. Site Mailing Address (page 11)	Street or P.O. Box: 665 Lybrand St.	PO Box 977				
	City, Town or Village: Postville					
	State: IA					
	Country: UNITED STATES	Zip Code: 52162				
8. Site Contact Person (page 11)	First Name: Jon MI: B	Last Name: Thorstenson				
	Phone Number: 5638644232 Extension:	Email Address:				
		jthorstenson@norplex-micarta.co				
9. Operator and Legal	Name of Site's Operator:	Date Became Operator (mm/dd/yyyy):				
Owner of the Site (pages 11 and 12)	Industrial Laminates/Norplex	09/15/1996				
	Operator Type: X Private County District Federal					
	Name of Site's Legal Owner: Honeywell	Date Became Owner (mm/dd/yyyy): 01/01/1982				
	Owner Type: X Private County District Federal	☐ Indian ☐ Municipal ☐ State ☐ Other				

Page 1 of 8

EPA Form 8700-13 A/B (Revised 09/2007)

by 18 MAR 2008



MAR 0 4 2008



9. Legal Owner (Continued)	Street or P.O. Box: 101 Columbia Rd			
Address	City, Town or Village: Morristown			
	State: NJ			
	Country: UNITED STATES		Zip	Code: 07962
10. Type of Regulated Mark "Yes" or "N	d Waste Activity o" for all activities; complete any additional boxes as instruc	ted. (Se	e inst	ructions on pages 13 to 16)
A. Hazardous Waste	Activities			
Complete all parts	for 1 through 6.			
. – –	erator of Hazardous Waste es", choose only one of the following - a, b or c.			2. Transporter of Hazardous Waste
	. LQG: Greater than 1000 kg/mo (2,200 lbs./mo.) of non-acute hazardous waste; or	Y []	N[X]	 Treater, Storer or Disposer of Hazardous Waste (at your site) Note: A hazardous waste permit is required for this activity.
	. SQG: 100 to 1000 kg/mo (220 - 2,200 lbs./mo.) of non-acute hazardous waste; or	Y 🗌	NX	4. Recycler of Hazardous Waste (at your site)
	 CESQG: Less than 100 kg/mo (220 lbs./mo.) of non-acute hazardous waste 	Υ	NX	5. Exempt Boiler and/or Industrial Furnace
In addition, in	dicate other generator activities.			a. Small Quantity On-Site
Y	United States Importer of Hazardous Waste			Burner Exemption b. Smelting, Melting, and Refining
Y	Mixed Waste (hazardous and radioactive) Generator	Υ□	NX	6. Underground Injection Control
B. Universal Waste A	ctivities		C.	Used Oil Activities
5,0 de	rge Quantity Handler of Universal Waste (accumulate 000 kg or more) [refer to your State regulations to termine what is regulated]. Indicate types of universal aste managed at your site. Mark all boxes that apply:	Υ[_ N [≥	Mark all boxes that apply. 1. Used Oil Transporter If "Yes", mark each that applies. a. Transporter b. Transfer Facility
b. F c. T d. L e. (f. C	Managed Batteries Pesticides Thermostats Lamps Other (specify) Other (specify) Other (specify)	Y[Y[Y[_ N [2	2. Used Oil Processor and/or Re-refiner If "Yes", mark each that applies. a. Processor b. Re-refiner 3. Off-Specification Used Oil Burner 4. Used Oil Fuel Marketer If "Yes", mark each that applies. a. Marketer Who Directs Shipment of Off-Specification Used Oil to
	estination Facility for Universal Waste ote: A hazardous waste permit may be required for this activity.			Off-Specification Used Oil Burner b. Marketer Who First Claims the Used Oil Meets the Specifications

11. Description of Hazardous Wastes (see instructions on page 17)							
A. Waste Codes for Federally Regulated Hazardous Wastes. Please list the waste codes of the Federal hazardous wastes handled at your site. List them in the order they are presented in the regulations (e.g., D001, D003, F007, U112). Use an additional page if more spaces are needed.							
D001	D002	D007	D008	D009	D018	D035	
F003	F005	U002	U122	U154	U159	U220	
	s for State-Regulated at your site. List them in			Please list the waste ons. Use an additional p	codes of the State-regulage if needed for more		
12. Comments (see instructions on page 17)							

13. Certification. I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

(See instructions on page 17)

Signature of owner, operator, or an authorized representative	Name and Official Title (type or print)	Date Signed (mm/dd/yyyy)
Jon Thorsman	Jon B Thorstenson, Manu. Engineer	03/03/2008
Jain Helbert	Jim Gilbert, Plant Manager	03/03/2008

1

sg

lbs/gal

49,432.000000

339,249.000000

ORM GM	U.S. ENVIRONME PROTECTION AGI 2007 Hazardous Waste WASTE GENERA AND MANAGEM
	WASTE GENERA
the instructions a	and forms booklet before
om cleanup	
zardous Waste Codes	s
Generated in 2007	G. UOM
388,681.000	Density Density
	ROCESS SYSTEM 2

Comments:

Site 1

Site 2

Site 3

VIRONMENTAL **CTION AGENCY**

ardous Waste Report

GENERATION **MANAGEMENT**

D. Total quantity shipped in 2007

D. Total quantity shipped in 2007

D. Total quantity shipped in 2007

PA Form 8700-13 A/B (Revised (09/2007))	Page 4 of
	_

No (FORM IS COMPLETE)

Shipped to

Shipped to

Shipped to

C. Off-site Management Method Code

C. Off-site Management Method Code

C. Off-site Management Method Code

H061

H061

X Yes (CONTINUE TO BOX B)

KSD980633259

ILD980613913

shipped

shipped

shipped

B. EPA ID No. of facility to which waste was

B. EPA ID No. of facility to which waste was

B. EPA ID No. of facility to which waste was

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION **U.S. ENVIRONMENTAL** LABEL OR ENTER: **PROTECTION AGENCY** SITE NAME: Industrial Laminates/Norplex 2007 Hazardous Waste Report **FORM WASTE GENERATION** EPA ID NO: IAD073489288 AND MANAGEMENT GM Instructions: Please see the detailed instructionson pages 18 to 26 of the instructions and forms booklet before completing this form. Waste Sec. 1 Still bottoms from batch still Description B. EPA Hazardous Waste Codes C. State Hazardous Waste Codes D001 F003 F005 D. Source Code E. Form Code F. Quantity Generated in 2007 G. UOM 1 G24 Density Management Method Code for Source 14,959.000000 Code G25 W200 lbs/gal sg Sec. 2 Was any of this waste managed on-site? (pages 24 and 25) Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) No (SKIP TO SEC. 3) **ON-SITE PROCESS SYSTEM 1 ON-SITE PROCESS SYSTEM 2** On-site Management On-site Management Quantity treated, disposed or Quantity treated, disposed or Method Code recycled on-site in 2007 Method Code recycled on-site in 2007 A. Was any of this waste shipped off-site in 2007 for treatment, disposal or recycling? (pages 25 and 26) Sec. 3 X Yes (CONTINUE TO BOX B) No (FORM IS COMPLETE) B. EPA ID No. of facility to which waste was C. Off-site Management Method Code D. Total quantity shipped in 2007 Site 1 shipped Shipped to KSD980633259 H061 8,368.000000 B. EPA ID No. of facility to which waste was C. Off-site Management Method Code D. Total quantity shipped in 2007 Site 2 shipped Shipped to ILD980613913 H061 6,591.000000 B. EPA ID No. of facility to which waste was C. Off-site Management Method Code D. Total quantity shipped in 2007 Site 3 shipped Shipped to Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION **U.S. ENVIRONMENTAL** LABEL OR ENTER: PROTECTION AGENCY SITE NAME: Industrial Laminates/Norplex 2007 Hazardous Waste Report **FORM WASTE GENERATION** EPA ID NO: IAD073489288 AND MANAGEMENT **GM** Instructions: Please see the detailed instructionson pages 18 to 26 of the instructions and forms booklet before completing this form. Waste Sec. 1 Ignitable liquid/solid mixture: contains rags, resin & cleanup solvent Description B. EPA Hazardous Waste Codes C. State Hazardous Waste Codes D001 F003 F005 E. Form Code G. UOM D. Source Code F. Quantity Generated in 2007 G13 Density Management Method Code for Source 9,379.000000 Code G25 W002 lbs/gal sq Was any of this waste managed on-site? (pages 24 and 25) Sec. 2 Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) No (SKIP TO SEC. 3) **ON-SITE PROCESS SYSTEM 1 ON-SITE PROCESS SYSTEM 2** On-site Management Quantity treated, disposed or On-site Management Quantity treated, disposed or Method Code recycled on-site in 2007 Method Code recycled on-site in 2007 A. Was any of this waste shipped off-site in 2007 for treatment, disposal or recycling? (pages 25 and 26) Sec. 3 X Yes (CONTINUE TO BOX B) No (FORM IS COMPLETE) B. EPA ID No. of facility to which waste was C. Off-site Management Method Code D. Total quantity shipped in 2007 Site 1 Shipped to shipped KSD980633259 H061 734.000000 B. EPA ID No. of facility to which waste was C. Off-site Management Method Code D. Total quantity shipped in 2007 Site 2 Shipped to shipped H061 ILD980613913 8,645.000000 B. EPA ID No. of facility to which waste was C. Off-site Management Method Code D. Total quantity shipped in 2007 Site 3 shipped Shipped to Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:					PROTE	IVIRONMENTAL CTION AGENCY	
SITE NAME: Industrial Laminates/Norplex				FORM		ardous Waste Report	
EPA ID N	NO: IAD073489288			GM		E GENERATION MANAGEMENT	
Instructions: Please see the detailed instructionson pages 18 to 26 of the instructions and forms booklet before completing this form.							
Sec. 1	Sec. 1 A. Waste Melamine resin/solvent & water from treater cleanup						
В. ЕРА Н	lazardous Waste Codes D001	F003	C. S	State Hazardous Wa	aste Codes		
D. Source		E. Form Code	F. C	F. Quantity Generated in 2007 G. UOM		G. UOM 1	
Management Method Code for Source Code G25 W113			69,347.000000 Density				
Sec. 2 Was any of this waste managed on-site? (pages 24 and 25) Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) No (SKIP TO SEC. 3)							
ON-SITE PROCESS SYSTEM 2 On-site Management							
Sec. 3 A. Was any of this waste shipped off-site in 2007 for treatment, disposal or recycling? (pages 25 and 26) X Yes (CONTINUE TO BOX B) No (FORM IS COMPLETE)							
Site 1	te 1 B. EPA ID No. of facility to which waste was shipped C. Off-si			agement Method Co	D. Total quantity	D. Total quantity shipped in 2007	
/	KSD980633259		Н0	061	382.000000		
Site 2	SITA / I		ite Mana ped to	agement Method Co	D. Total quantity	D. Total quantity shipped in 2007	
	ILD980613913		Н0)61		68,965.000000	
Site 3 B. EPA ID No. of facility to which waste was shipped C. Off-site Shipper			agement Method Co	ode D. Total quantity	shipped in 2007		
Comments:							

EPA ID NO:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Industrial Laminates/Norplex

IAD073489288

FORM

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 Hazardous Waste Report

WASTE GENERATION AND MANAGEMENT

			O.III				
Instructions: Please see the detailed instructionson pages 18 to 26 of the instructions and forms booklet before completing this form.							
Sec. 1 A. Waste Part washer solvent / particulates Description							
B. EPA Hazardous Waste Codes D039	C.	C. State Hazardous Waste Codes					
D. Source Code G13		F.	F. Quantity Generated in 2007 G. UOM 1		1		
Management Method Code for Source Code G25	W202			71.000000	Density		
Sec. 2 Was any of this waste managed on-site? (pages 24 and 25) Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) X No (SKIP TO SEC. 3)							
ON-SITE PROCESS SYSTEM 1 On-site Management Method Code ON-SITE PROCESS SYSTEM 2 On-site Management Method Code On-site Ma							
Sec. 3 A. Was any of this waste shipped o X Yes (CONTINUE TO BOX B)	_	treatment, DRM IS CC		? (pages 25 and 26)			
		hipped to	nagement Method Cod	de D. Total quantit	D. Total quantity shipped in 2007 71.000000		
B. EPA ID No. of facility to which waste was C. Off-site			nagement Method Cod	de D. Total quantit	D. Total quantity shipped in 2007		
Sito 3		Off-site Mar hipped to	nagement Method Cod	de D. Total quantit	D. Total quantity shipped in 2007		
Comments:							